


Fíg. 1



Fíg. 2




Fig. 3

EXPOSE SAW OR BLADE DEVICE TO MEASUREMENTS

402

ACQUIRE INFORMATION

404

EXCITE SAW OR BLADE DEVICE WITH OTHER MODE(S)

406

SEPARATE THE MEASURAND(S)
FROM THE SENSOR SURFACE

408

READY FOR NEXT TEST

410

Fíg. 4